

**Pavement Management Program
2017 Proposed List Of Roadway Improvements
(List Subject To Change Due To Availability Of Funding And Weather Conditions)**

Name	From	To	Length (linear feet)	Width	PCI	Assigned Resources	Repair Strategy
Atwater Road	Maple Avenue	585' S of Thayer Avenue	1728	18	88	Vendor	Thin Overlay
Country Lane	Torrington Avenue	Country Lane	5,062	26	57	Vendor/DPW	Mill/Overlay w/drainage
Freedom Drive	Torrington Avenue	Cul De Sac	3,027	24	64	Vendor/DPW	Mill/Overlay w/drainage
Millenium Field Parking Lot						Vendor/DPW	Overlay w/drainage
Various Roads						Vendor	Crack Seal
Full Dept Patching/Misc. Drainage						DPW	
Testing and Engineering Services						Vendor	
<i>Totals</i>			<i>9,817</i>	<i>1.86</i>	<i>miles</i>		